



- Please replace the marked parts with the parts from the update kit

- Please make sure to install the freewheel distance bushing (highlighted red)

- Please remove bearing reducers from MTB and E-MTB 6-bolt rear hubs

- after assembling the update kit it is NOT compatible with MicroSpline drivers

- please view the video „NEWMEN Evolution 2019 hub service (GEN2)“ on our website for detailed assembly instructions